

Download Bmw 320i E46 M54 Repair Manual

Here we have the round type rocker cover to fit the BMW 2vR series. This is a good pattern copy of the original BMW rocker cover. Motorworks UK are the UK's largest independent supplier of new and use...Changes from 2000 to 2001. 323i is replaced by the 325i and receives a the new M54 2.5L engine with 184hp & 175lb/ft of torque. 328i is replaced by the 330i and receives a the new M54 3.0L engine with 225hp & 214lb/ft of torque. Owen: Comments: hi, been living with a po340 code for a while now. i replaced the intake sensor with a delphi branded one which i was told was good quality. it seemed to solve it initially but it came back pretty quick. the fault all started from an oil change weird i know. after it was stalling out randomly, loss of power low down and poorer mpg. I only get the code from a cold start. if i ...BMW Fault Codes Repair Code Description of Repair 00110170 E34/E38 M60B30 Secondary air shutoff valve 00110171 E31/32/34/38 M60 automatic USA piston ring wear detectors