

Download Chevy 1500 2wd Repair Manual

"Chilton Repair Manual --CHILTON REPAIR MANUAL, FOR 1980-1987 GENERAL MOTOR FULL-SIZE TRUCKS. Covers 2WD and 4WD Models with gasoline and diesel engines; Chevrolet Blazer, C10, C20, C30, K10, K20, K30...I have 1990 chevy c1500 with bad getrag 5 speed manual trans. can it be replaced with a diferent type of trans. - Answered by a verified Chevy MechanicCheck your fuses first. GM's have 2 fuses for the blower motor. One for high speed only and another fuse for the other speeds. The resistor block should be located next to the blower motor under the passenger's side of the dash. There's 2 screws that hold it in place. Hope that helps. Jim ...The camshaft position sensor (also known as the distributor pickup) is inside the distributor which is driven by the camshaft gear and directly below the water pump, the water pump must be removed to access the distributor to change the sensor. Here is a picture of the camshaft position sensor ...