

Download Repair Manual 92 Chevy Lumina Euro

My 92 Lumina did the same thing mine turned out to be the ignition coils they would measure in the good zone but after heating up they would be out of specks since I replaced them I haven't had a problem since. there should be 3 of them located on the front of the engine you may have to buy a special socket to replace them all in all about \$100.00 My Chevy Lumina will not start hot, runs/idles rough - I have a 1996 Chevy Lumina LS, 3.1 V6. Over the last 18 months I have had problems with it getting h... Auto parts, new, Auto Parts, used: Nissan engine and transmission 1997 Cadillac Sts emblems. Salvage yard switch combination KIA. switch auto parts, new, starter salvage yard 1967 Cadillac generator regulator. switch auto parts, new, transmission tail light pc board 1986 Volvo 240. Our policy is to keep a comprehensive range of "stock" (bread and butter) service items such as spark plugs, brake pads, distributor caps and water pumps on the shelf - no easy task when attempting to cover every American make!